

BLTouch Firmware Version for 32-bit Motherboard

Model	Condition 1	Condition 2	Firmware Version
Ender-3	4.2.2 32-bit Motherboard Firmware	BLTouch without Adapter Board	Ender-3- Marlin2.0.1 - V1.1.2 - ALT
		BLTouch with Adapter Board	Ender-3 - Marlin2.0.1- V1.3.1- ALT
		BLTouch with Adapter Board + Filament Sensor	Ender-3 - Marlin2.0.1- V1.4.1- ALT - Filament
	4.2.7 32-bit Motherboard Firmware	BLTouch without Adapter Board	Ender-3- Marlin2.0.1 - V1.1.2 - ALT - TMC2225
		BLTouch with Adapter Board	Ender-3 - Marlin2.0.1- V1.3.1- ALT - TMC2225
		BLTouch with Adapter Board + Filament Sensor	Ender-3 - Marlin2.0.1- V1.4.1- ALT - Filament - TMC2225
Ender-3MAX	4.2.2 32-bit Motherboard Firmware	BLTouch without Adapter Board	Ender-3 Max - V1.0.1.6 - ALT
	4.2.7 32-bit Motherboard Firmware	BLTouch without Adapter Board	Ender-3 MaxMarlin2.0.6HW4.2.7ALT
Ender-3Pro	4.2.2 32-bit Motherboard Firmware	BLTouch without Adapter Board	Ender-3 Pro- Marlin2.0.1 - V1.1.2 - ALT
		BLTouch with Adapter Board	Ender-3 Pro - Marlin2.0.1 - V1.3.1 - ALT
		BLTouch with Adapter Board + Filament Sensor	Ender-3 Pro - Marlin2.0.1 - V1.4.1 - ALT - Filament
	4.2.7 32-bit Motherboard Firmware	BLTouch without Adapter Board	Ender-3 Pro- Marlin2.0.1 - V1.1.2 - ALT - TMC2225
		BLTouch with Adapter Board	Ender-3 Pro - Marlin2.0.1 - V1.3.1 - ALT - TMC2225
		BLTouch with Adapter Board + Filament Sensor	Ender-3 Pro - Marlin2.0.1 - V1.4.1 - ALT - Filament - TMC2225
Ender-3V2	4.2.2 32-bit Motherboard Firmware	BLTouch without Adapter Board	Ender-3 V2-Marlin2.0.1 - V1.3.1 - ALT
		BLTouch with Adapter Board	Ender-3 V2-Marlin2.0.1-HW-4.2.2-mainboard-V1.1.2-Compatible with ALT and filament detection
		BLTouch+Filament Sensor	Ender-3 V2-Marlin2.0.1-HW-4.2.2-mainboard-V1.1.2-Compatible with ALT and filament detection
	4.2.7 32-bit Motherboard Firmware	BLTouch without Adapter Board	Ender-3 V2-Marlin2.0.8_HW_V4.2.7_SW_V2.0.8.4_ALT_Zh_CN_en_20210802
		BLTouch with Adapter Board	Ender-3 V2-Marlin2.0.1 - V1.3.1 - ALT - TMC2225
		BLTouch+Filament Sensor	Ender-3 V2-Marlin2.0.1-HW-4.2.7-mainboard-V1.1.2-compatible with ALT and filament detection
Ender-5, 5S	4.2.2 32-bit Motherboard Firmware	BLTouch without Adapter Board	Ender-5- Marlin2.0.1 - V1.1.1 - ALT
		BLTouch with Adapter Board	Ender-5 - Marlin2.0.1 - V1.3.1- ALT
		BLTouch with Adapter Board + Filament Sensor	Ender-5 - Marlin2.0.1 - V1.4.1- ALT - Filament
	4.2.7 32-bit Motherboard Firmware	BLTouch without Adapter Board	Ender-5- Marlin2.0.1 - V1.1.1 - ALT - TMC2225
		BLTouch with Adapter Board	Ender-5 - Marlin2.0.1 - V1.3.1- ALT - TMC2225
		BLTouch with Adapter Board + Filament Sensor	Ender-5 - Marlin2.0.1 - V1.4.1- ALT - Filament - TMC2225
Ender-5Pro	4.2.2 32-bit Motherboard Firmware	BLTouch without Adapter Board	Ender-5 ProMarlin2.0.6HW4.2.2ALTE137
		BLTouch with Adapter Board	Ender-5 Pro- Marlin2.0.1 - V1.3.1 - ALT
		BLTouch with Adapter Board + Filament Sensor	Ender-5 Pro- Marlin2.0.1 - V1.4.1 - ALT - Filament
	4.2.7 32-bit Motherboard Firmware	BLTouch without Adapter Board	Ender-5 Pro- Marlin2.0.1 - V1.1.1 - ALT - TMC2235
		BLTouch with Adapter Board	Ender-5 Pro- Marlin2.0.1 - V1.3.1 - ALT - TMC2225
		BLTouch with Adapter Board + Filament Sensor	Ender-5 Pro- Marlin2.0.1 - V1.4.1 - ALT - Filament - TMC2225
Ender-5plus	BLTouch Firmware	BLTouch Firmware	Ender-5PlusALT_V1.70.2 BL.hex
CR-10	4.2.7 (32-bit Silent Motherboard)	BLTouch without Adapter Board	CR-10-Marlin2.0.1-20201207-HW-V4.2.7-SW-V1.1.1 ALT-English
Ender-6	BLTouch Firmware	BLTouch Firmware	Ender-6-V1.0.4.9-ALT
Ender-7	BLTouch Firmware+Touchscreen Firmware	BLTouch Firmware+Touchscreen Firmware	Ender-7-hw-V24S1_101-sw-V2.0.1-ALT DWIN_SET
Sermoon D1	BLTouch Firmware+Touchscreen Firmware	BLTouch Firmware+Touchscreen Firmware	firmware_V1.0.8-ALT DWIN_SET
CR-200B	BLTouch Firmware+Touchscreen Firmware	BLTouch Firmware+Touchscreen Firmware	firmware202108100905-ALT DWIN_SET